



LEGEND

Drainage Issues

Sewer Issues

Pedestrian Issues

Driving Issues

Cycling Issues

Miscellaneous Issues

Fire Station

Playground

School

?

One Way Street Direction

71

Address

@

Catch Basin

02550100150200

Feet

## GLOBAL ISSUES

- DRAINAGE ISSUES

MANY PROPERTIES WITH FLOODING.

MANY PROPERTIES WITH UNDERGROUND STREAMS PRESENT UNDER HOUSES.

RECENT CHANGES TO HURON AVE REDIRECTED FLOW, CAUSING PONDING IN BACKYARDS ON LEXINGTON AVE.
- SEWER ISSUES

NONE REPORTED.
- PEDESTRIAN ISSUES

DIFFICULT TO MANUEVER STROLLERS AND WHEELCHAIRS IN NEIGHBORHOOD.

CONCRETE AND BRICK SIDEWALK HEAVING AND PROBLEMS WITH PEDESTRIAN ACCESS DUE TO TREE/SIDEWALK CONFLICTS. SIDEWALK MATERIAL IS A CONCERN. NEIGHBORHOOD SIGNED PETITION TO HAVE BRICK, BUT BRICK IS HEAVING.
- DRIVING ISSUES

ONE WAY CAN BE CHALLENGING FOR RESIDENTS IN THE NEIGHBORHOOD.

POTHoles ARE ALL OVER LEXINGTON AVENUE.

CONCERNED ABOUT POTENTIAL LOSS OF STREET PARKING.
- CYCLING ISSUES

CONCERNS WITH SAFETY FOR CYCLISTS.

ONE WAY CAN BE DIFFICULT FOR CYCLISTS; CONSIDER TWO WAY TRAFFIC.
- MISCELLANEOUS ISSUES

SNOW PLOWING IS AN ISSUE.

CONCERNED WITH MAINTENANCE OF GRASS STRIP IF GRASS STRIP IS INCLUDED IN THE DESIGN.

## GLOBAL SUGGESTIONS

- PEDESTRIAN SUGGESTIONS

CONSIDER DIFFERENT SIDEWALK TREATMENT OPTIONS

- BRICK EDGING

- CONCRETE

- CONCRETE WITH BRICK EDGE
- SUGGEST WIDER SIDEWALKS.